## 57412

## CALIFORNIA HAZARDOUS WASTE MANIFEST State Department of Health Services

1 Manifest 0 1 5 See reverse side for Instructions. HAZARDOUS MATERIALS MANAGEMENT SECTION , Number Please type or print clearly. Press Hard. 744 P Street, Sacramento, CA 95814 GENERATOR (Generator Must Complete) (3) Designated TSD Facility (Authorized to operate under an (4) Alternate TSD Facility SFUND RECORDS CTR approved state program or federal program) CHEMICAL WASTE 999000940 ALUMINUM CO. OF AMERICA (2) Name VERNON, WORKS Name OPERATING INDUSTRIES Nam MANAGEMENT EPA NO. EPA NO. EPAINO. Address 5151\_ALCOA\_AVE Phone No 588-6141 Address 900 N. POTRERO GRANDE DR Address P.O. BOX 1104 430 W. ELM AVE City, State, Zip VERNON, CA City, State, Zip MONTEREY PARK, CA. City, State, Zip COALINGA. CA. U.S. DOT Hazard Class UN/NA WEIGHT OR U.S. DOT PROPER SHIPPING NAME UNITS ID NO. VOLUME **CONTAINERS NUMBER:** TYPE: DRUMS BAGS CARTONS WASTE ☐ TANK TRUCK ☐ DUMP TRUCK WASTE □ OTHER (8) GENERATING PROCESS ALUMINUM FABRICATION 6 ) WASTE CATEGORY\_ EX. HAZ. WASTE PERMIT NO. CONC. RANGE RANGE LOWER LIST COMPONENTS: UNITS (9) A. □ % □ ppm. Non Hazardous Material \_\_\_\_\_% ☐ Toxic ☐ Flammable ☐ Corrosive/Irritant ☐ Reactive ☐ Sensitizer ☐ Carcinogen/Mutagen DO Other ALUMINUM OXIDES & WATER (11) PHYSICAL STATE: 🔲 Solid X Liquid X Sludge ☐ Slurry ☐ Gas (12) SPECIAL HANDLING INSTRUCTIONS: ☐ Gloves ☐ Goggles ☐ Respirator Other \_\_\_\_ GENERATOR CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked, labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and EPA. IN THE EVENT OF A SPILL, CONTACT THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 1-800-424-8802 gnature of Authorized Agent and Fitle TRANSPORTER (HAULER MUST COMPLETE) (14) NAME \_ ASBURY OIL CO. CAD028277036 EPA NO. ADDRESS 13419 Halldale Avenue PHONE NO. (213) 321-1392 CITY, STATE, ZIP Gardena, California 90249 TSD FACILITY (FACILITY-OPERATOR MUST COMPLETE) 2 18 QUANTITY (If Measured) HANDLING OR DISPOSAL METHOD: EPA NO. STATE FEE (If Anv) ☐ Surface Impoundment ☐ Candfill PHONE NO. ☐ Injection Well ☐ Land Treatment (20) INDICATE ANY SIGNIFICANT DISCREPANCIES BETWEEN MANIFEST AND ☐ Treatment (Specify). SHIPMENT: ☐ Recovery or Reuse ☐ Storage/Transfer IF WASTE IS HELD FOR DELIVERY ELSEWHERE, SPECIFY THE DESIGNATED TSD FACILITY: (22) NAME EPA NO. Signature of Authorized Agent and Date Accepted AD LC INIAL